



#60

45,600 min<sup>-1</sup>




G3236

36,000 min<sup>-1</sup>




G3237



砥粒の材質 結合剤 結合度  
 A フルー V P


#80

105,000 min<sup>-1</sup>



G3241


95,000 min<sup>-1</sup>



G3242

#60

88,000 min<sup>-1</sup>




G3243

一般鋼材、鋳物、鋳鋼、鋳造品、炭素鋼（生材）（一般ハンドグラインダー用）


#60

72,000 min<sup>-1</sup>




G3244

62,400 min<sup>-1</sup>




G3245

45,600 min<sup>-1</sup>




G3246

36,000 min<sup>-1</sup>




G3247



砥粒の材質 結合剤 結合度  
 GC V J

105,000 min<sup>-1</sup>




G3251

超硬合金、特殊鋳鉄、ガラス、陶磁器、石材（一般ハンドグラインダー用）


#100

95,000 min<sup>-1</sup>




G3252

88,000 min<sup>-1</sup>




G3253

72,000 min<sup>-1</sup>




G3254

62,400 min<sup>-1</sup>




G3255

45,600 min<sup>-1</sup>



G3256

36,000 min<sup>-1</sup>



G3257

■安全のため突出し長さに注意し、最高使用回転数以下でご使用ください。 ■安全のため、保護メガネをご使用ください。  
 ■寸法・仕様等を予告なく変更する事があります。